



Test Conditions: Observe the humidity change in an unloaded XD2-502-01 for 72 hours. Test Result: The humidity level in XD2-502-01 is maintained at an average of 1% after the RH levels become stable below 5% to satisfy the IPC/JEDEC (both 033 and 020) standards.

Humidity Setting	1.0%RH
Average Humidity	1.0%RH
Minimum Humidity	0.3%RH
Maximum Humidity	2.9%RH